

# RECALL NOTICE

## Marker Recalls 2017-2018 Kingpin 10 and 13 Touring bindings toe parts




KINGPIN 10 & 13  
GOLD



KINGPIN 10 & 13  
COPPER

**Hazard:** The Pin in the toe part can break under rare circumstances. This can lead to reduced release/retention and can result in a fall hazard.

### **Recalled Products:**



With this serial number on the heel you are able to find out if your binding is affected or not. If your serial number is in between this range you should replace the toe part.

KingPin 10  
→ 337804 – 418632

KingPin 13  
→ 337798-411728

**Remedy:** Check with Marker or your Marker Authorized Retailer for details.

Stop using these bindings and return them to a Marker Authorized Retailer to determine if they are covered by this recall. Toe pieces of recalled bindings will be replaced at no charge.

### **For more Information:**

[ 514-745-2002#325]

[[kingpinrecall@tecnicagroup.ca](mailto:kingpinrecall@tecnicagroup.ca)]

And go to [www.tecnicagroup.ca/kingpinrecall](http://www.tecnicagroup.ca/kingpinrecall)

This recall is being conducted in cooperation with several government consumer safety organizations.